



Nassau County Fire Commission

Office of the Fire Marshal

1194 Prospect Avenue

Westbury, N.Y. 11590

(516) 573-9900

nassaucountyny.gov/firemarshal

Non-compliant Automatic Fire-Extinguishing System Procedure

To Whom It May Concern;

Only systems listed to UL 300 and on this list are considered serviceable. All others must be replaced.

- Amerex KP275, KP375, KP475, KP600
- Ansul R-102 1.5 gallon, 3.0 gallon post 1998 (in most cases stainless cylinder only)
- Badger Range Guard RG-1.25G, RG-2.5G, RG-4G(S|M|L), RG-6G
- Buckeye Kitchen Mister BFR-5, BFR-10, BFR-15, BFR-20
- Heiser Protex II L1600, L3000, L4600, L6000
- Kidde WHDR-125, WHDR-260, WHDR-400(S|M|L), WHDR-600
- Lehavot WCK 6, WCK 9, WCK 16, WCK 20, WCK 26
- Pyro-Chem Kitchen Knight II PCL-160, PCL-300, PCL-460, PCL-600

Additional reasons for red-tagging and marking a system as non-compliant include but are not limited to:

- Cylinder needs to be hydro-tested
- Unprotected cooking equipment under the hood
- Clogged or missing nozzles, piping, pulleys, etc
- Broken link lines, pipes, etc.
- Anything that does not conform to manufacturers' specifications or would prevent complete operation or protection of the system

The following process shall be followed by all contractors when encountering a non-compliant automatic fire-extinguishing system in Nassau County.

1. Inform the proprietor that the system is non-compliant and the steps necessary to correct the issue.
2. Tag the system with a non-compliant tag. This tag shall be red in color and shall contain:
 - a. Licensed contractor's name, address, phone number and license number.
 - b. Printed name of service person or technician.
 - c. Signature of service person or technician.
 - d. Pre-printed day and month of service, both of which shall be punched. Year may be written.
 - e. The location ID assigned by the Nassau County Fire Marshal's Office.
 - f. The permit number assigned by the Nassau County Fire Marshal's Office.
 - g. Date of agent cylinder hydrostatic test.
 - h. Agent cylinder model number and serial number.
 - i. Nature of the impairment.
3. Leave the last service tag on the system cylinder.
4. Fill out a work report in its entirety and fax to (516) 573-9072 within 24 hours.
5. Ensure that the proper fire extinguishers are present, charged and have been serviced.